








INSTALLATION QUICK REFERENCE SELECTION CHART

INSERT SERIES	PHOTO	INSTALLATION METHOD			
		ULTRASONIC	THERMAL/HEAT	MOLD-IN	PRESS-IN
H-SERIES					
C-SERIES					
HC-SERIES					
S-SERIES					
P & HP SERIES					
E & HE SERIES					
MB SERIES					

	PRIMARY INSTALLATION METHOD
	THIS METHOD CAN ALSO BE USED
	CAN BE USED BUT CAUTION SHOULD BE TAKEN NOT TO OVER WELD
	THIS METHOD IS NOT RECOMMENDED